


TRILUX




Montageanleitung
Mounting instructions
Instructions de montage
Istruzioni di montaggio
Instrucciones de montaje

545/E14





- Ⓓ Leuchten mit 545/E14 bestückbar
- ⒼⒸ Luminaires can be equipped with 545/E14
- Ⓕ Luminaires peuvent être équipés de 545/E14
- Ⓘ Apparecchi possono essere equipaggiati con 545/E14
- Ⓔ Luminarias pueden ser equipados de 545/E14


3501N	5062 R...	72.2 PS/1x36
3601	5063 R...	7222 SB
3602	5081	7224 RPV/3x
3604	5082	7224 SB/3x
3652.../TC18	5084	7232 SB
3662.. R...	5221	7234 SB/3x36
3663 RST	5231	
3771N	540.N	
3772	545.N	




- Ⓓ Orientierung des Klemmenträgers
- ⒼⒸ Orientation of terminal holder
- Ⓕ Orientation du support de bornier
- Ⓘ Orientamento del supporto morsettiere
- Ⓔ Orientación del soporte del borne




- Ⓓ Mitte des Rasterverschlusses im Leuchtenkörper
- ⒼⒸ Middle of the louvre clip in luminaire body
- Ⓕ Centre de la fermeture de l'optique dans le corps du luminaire
- Ⓘ Centro della chiusura dell'ottica nel corpo dell'apparecchio
- Ⓔ Centro del cierre de la óptica en el cuerpo de luminaria



- Ⓓ T-Schlitz bei Einbauleuchten
- ⒼⒸ T-slot with recessed luminaires
- Ⓕ Rainure en T pour luminaires encastrés
- Ⓘ Fessura a T con apparecchi da incasso
- Ⓔ Ranura en T para luminarias empotrables




- Ⓓ Positionierung der Zusatzbeleuchtung bei TC-Lampen
- Ⓖ Positioning of additional lighting with compact fluorescent lamps
- Ⓕ Positionnement de l'éclairage additionnel pour lampes fluorescentes compactes
- Ⓘ Posizionamento dell'illuminazione addizionale con lampade fluorescenti compatte
- Ⓔ Situación de la iluminación adicional para lámparas fluorescentes compactas




- Ⓓ Positionierung der Zusatzbeleuchtung und des Klemmenträhers
- Ⓖ Positioning of additional lighting and terminal holder
- Ⓕ Positionnement de l'éclairage additionnel et du support de bornier
- Ⓘ Posizionamento dell'illuminazione addizionale e del supporto morsettiera
- Ⓔ Situación de la iluminación adicional y del soporte del borne

35..., 36..., 37...




52...


50...






54...




72...





- Ⓓ Montage
- Ⓖ Mounting
- Ⓕ Montage
- Ⓘ Montaggio
- Ⓔ Montaje






- 3
- Ⓓ Klemmenträger mit Klebestreifen positionieren (Abbildungen A - D auf Seite 1 und 2 beachten).
 - Ⓖ Position the terminal holder with adhesive tape (observe illustrations A - D on pages 1 and 2).
 - Ⓕ Positionner le support de bornier en utilisant le papier collant (illustrations A - D sur les pages 1 et 2).
 - Ⓘ Posizionare il supporto del morsetto con nastro adesivo (vedi figure A - D su pagina 1 e 2).
 - Ⓔ Orientar y sujetar el soporte del borne mediante la cinta adhesiva (ver las ilustraciones A - D en las págs. 1 y 2).





- 4..
- Ⓓ Zusatzbeleuchtung positionieren.
 - Ⓖ Position additional lighting.
 - Ⓕ Positionner l'éclairage additionnel
 - Ⓘ Posizionare illuminazione supplementare.
 - Ⓔ Posicionar la iluminación adicional.



7224 RPV/3x
7234



4c



- Ⓓ Beim Einsetzen des Rasters keine basisisolierten Leitungen berühren.
- Ⓔ When inserting the louvre do not touch any basic insulated wires.
- Ⓕ Lors du montage de l'optique faire attention à la filerie à isolation principale.
- Ⓖ Inserendo l'ottica non toccare le linee dotate di isolamento di base.
- Ⓗ Al montar la óptica no tocar los cables de aislamiento de base.

TRILUX-LENZE GmbH+Co KG
Postfach 1960, D-59753 Arnsberg
Telefon +49 (0) 2932 /301-0
Telefax +49 (0) 2932 /301-375