

iTorque

DE Einheit wechseln
EN Replacing the unit
FR Changement d'unité

Verändern des Einstellwertes
Modifying the setting value
Modification de la valeur de réglage

Wichtig!
Important!
Important!

Zählerstand anzeigen
Displaying counter reading
Affichage de l'état du compteur





Reset nach Kalibrierung
Reset after calibration
Reset après calibration

Gebrauchsanweisung
User manual
Mode d'emploi







wiha Wiha
Tools that work for you

Wiha Werkzeuge GmbH
Obertalstraße 3-7
78136 Schonach/ Germany
www.wiha.com






Nm	in.lb
40 - 150 cNm	60 - 210 in.oz
0.8 - 3.0	7.0 - 26.0
1.0 - 5.0	9.0 - 44



Einstellwerkzeug
Adjustment tool
Outil de réglage



nur für / only for / seulement pour
1.0 - 5.0 Nm




Kalibrieralarm
Calibration alarm
Alarme de calibration



Wiha Werkzeuge GmbH
www.wiha.com/services



Batteriestatus
Battery status
Etat de la pile



Wiha Werkzeuge GmbH
www.wiha.com/services

